Work Orde January 20, 201												Page
Revision ID:	D4050-8 Strut 1/20/10 1/25/10	Start Q	ety: 1.00 Qty: 1.00			Cust Item I			s s	Setup Sta	1 18011191 1	
Reference:	Process QC:	Plan:		Date: <u>//</u> /	20Tooling: SPC (Y/N):	Da	ite:		F	tun Sta Sto		
Sequence ID/ Work Center II		Operation Niver	tion	nnri	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr D4050		Revision Nbr PA2	-	PKLL	.IIWIINAKY	1990F						
100 		NC BRAK	Memo	Dwg. D4050 and Spec Co	0.00 0.00 ontrol Dwg D2638	34.23 DB 10	loc/ac		0			
110 		Small Fab	Memo Deburr		0.00			/	J)	10 fb	//21	

120 QC Quality Control

Memo

QC5- Inspect part completeness to step on W/O

W/O:			WO	RK ORDER CHANG	iES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No: PAR #:		Fault Categ	ory:	_ NCR: Ye	s No I	DQA:	QA: Date:		
Resolution:			Disposition	:	QA: N/C	QA: N/C Closed:			
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (N	CR)			
DATE	STEP	Description of NC	Initial	tion B		rification	Approval	Approval	
		Section A	Chief Eng	Action Description Chief Eng	Da		Section C	Chief Eng	QC Inspector

WOOZD



January 20, 20								rag
Item ID: Revision ID: Item Name:	D4050-8 Strut			Accept			Setup Star	
Start Date: Required Date Reference:	1/20/10 : 1/25/10	Start Qty: 1.00 Req'd Qty: 1.00			Cust Item ID: Customer:			
Approvals:	Process Pla	ın:	Date:	Tooling: SPC (Y/N):	Date:		Run Star Sto	
Sequence ID/ Work Center I 130 Powdercoat Powder Coating	ID	Memo START TIM	1) per QSI005 4.3-Steel M ((3170) ME: 12:45,000 MERATURE: 14000 ME: 1:15,000	Set Up/ Run Hours 0.00	Draw Draw Number Rev.	Plan Acc Code Qty	•	Reject Insp. Number Stamp
QC Quality Control		QC3- Inspect Part Finish Memo		0.00	10-01-21	Ø	_P	

150

Packaging

Packaging

Identify as per dwg & Stock Location:_____

Memo

0.00

0.00

POSITIVE RECALL

EFFECTIVE AUTH

RELEASED _____ DATE ____

W/O: DATE STEP			WC	ORK ORDER CHAN	GES				
DATE	STEP	PRO	PROCEDURE CHANGE						Approval QC Inspector
				W- 11.					
Part No: PAR #: Resolution:			Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:	
			Dispositio	n:	QA: N/C	QA: N/C Closed: Da)ate:
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	Initial	Corrective Action Se Action Description	ection B		cation	Approval	Approval
		Section A	Chief Eng	Chief Eng	Dat		ion C	Chief Eng	QC Inspector
									*
								i i	

Work Order ID 55547

Page 3

January 20, 2010 10:43:06 AM

Item ID:

`

D4050-8

Accept



Setup Start

Stop



Required Date: 1/25/10

Revision ID:

Item Name: **Start Date:**

Strut

1/20/10

QC:

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Date:

Tooling: SPC (Y/N):

Set Up/

Date:

Number

Date:

Start Run

Stop

Sequence ID/ **Work Center ID**

160

QC

Quality Control

Operation Description

QC21- Final Inspection - Work Order Release

Memo

Run Hours

0.00

0.00

Draw Draw

Rev.

Plan

Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector
,									
Part No: PAR #:									
Resolution:				on:	ed: Date:				
NCR:			WORK ORI	DER NON-CONFORMA	ANCE (NC	R)			
DATE	STEP	Description of NC	Corrective Action Section B			Ver	ification	Approval	Approval
	J. L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat		ection C	Chief Eng	QC Inspector
	İ								
								; f	

January 20, 2010 10:43:11 AM

Work Order ID: 55547

Parent Item:

Comments:

D4050-8

Parent Item Name: Strut

IPP RevA: new issue DD 10.01.20 verified by:EC

Start Date: 1/20/10

Required Date: 1/25/10

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
M304TR0.750W.049		Purchased	No			100	f	326.9924	2.9324			

304 RD Tube .750 x .049W

Warehouse	Loc Oty	Loc Code			
Location					
Main Warehouse					
MAT	326.9924				*
107518	2.77				
108498	0				
109314	8.5				
110113	0.73				
110271	0.03				
111096	9		<u> </u>		
111457	11.43			_	
112652	85.89			2 1 1 2	65
112800	208 6424		3.100 8	\$ 1010(12)	U

	T .	-									
W/O:			WORK ORDER CHANGES								
DATE STEP		PRO	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
Part No: PAR #:		PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:	: Date:				
		esolution:	Disposition	າ:	_ QA: N/C CI	Date: _	_ Date:				
NCR:		V	VORK ORDE	ER NON-CONFORMA	NCE (NCF	R)					
DATE		Description of NC		Corrective Action Section		Verification	rification Approval	Approval			
DATE	SIEP	STEP Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Chief Eng	QC Inspector			
							:				
	-			770000							

